


## **Category C - Phase II of GWF Tracy**

- b)** A three-phase fault with the normal 6-cycle clearing time on the  
2) Tesla 230 kV Bus 2, Sect. D

Plot 1	Project Terminal Voltages and Angles
Plot 2	Project Power and Speed
Plot 3	Selected Bus Voltages Adjacent to Fault
Plot 4	Selected Bus Frequencies Adjacent to Fault




ENF Tracy Peaking Plant Project (Phase 2 - 258 MW)

2004 Summer Peak Base Case, Stability Study

Phase 2 w/ ENF CT 1 & 2 and ST each @ 86.0 MW

3 Phase 6 cycle fault at the Tesla 230 kV bus followed loss of Bus 2 Section D.




ENF Tracy Peaking Plant Project (Phase 2 - 258 MW)

2004 Summer Peak Base Case, Stability Study

Phase 2 w/ ENF CT 1 & 2 and ST each @ 86.0 MW

3 Phase 6 cycle fault at the Tesla 230 kV bus followed loss of Bus 2 Section D.




GWF Tracy Peaking Plant Project (Phase 2 - 258 MW)

2004 Summer Peak Base Case, Stability Study

Phase 2 w/ GWF CT 1 & 2 and ST each @ 86.0 MW

3 Phase 6 cycle fault at the Tesla 230 kV bus followed loss of Bus 2 Section D.



GWf Tracy Peaking Plant Project (Phase 2 - 258 MW)

2004 Summer Peak Base Case, Stability Study

Phase 2 w/ GWF CT 1 & 2 and ST each @ 86.0 M

3 Phase 6 cycle fault at the Tesla 230 kV bu

Bus 2 Section D.